


**HS08** and **HS13** are disabled to meet 15 USB port limit in macOS. No USB 2.0 devices will connect here. **SSP1** and **SSP2** are controlled by Thunderbolt and do not count against 15 port limit.



**HS01** is disabled to meet 15 USB port limit in macOS. No USB 2.0 devices will connect here.

**HS01/SS01**  
Front Panel USB 3.1 Gen 2 Type C

**HS05/SS05**  
Front Panel USB 3.1 Port 1

**HS06/SS06**  
Front Panel USB 3.1 Port 2

**HS14**  
Intel CNVi Bluetooth (disabled)

**HS11/HS12:**  
Two USB 2.0 ports

**HS06/SS06:**  
**USB 3.0**

**HS05/SS05:**  
**USB 3.0**

**SS01/HS01:** USB 3.1  
**Gen 2 Type-C**

**HS01** is disabled to meet 15 USB port limit in macOS. No USB 2.0 device will connect here.

