









HS / SS	USB	USB Port	Fractal Design	Port (Gigabyte Manual)	Motherboard Header	USB Connector Type
HS01	USB 3.1 Gen2	B3	F1	#15	F_USB31C	9
HS02						
HS03	USB 3.1 Gen2	3				3
HS04	USB 3.1 Gen2	4				3
HS05	USB 3.1 Gen1	B2	F4	#16	F_USB30	3
HS06	USB 3.1 Gen1	B2	F5	#16	F_USB30	3
HS07	USB 3.1 Gen1	5				3
HS08						
HS09	USB 2.0/1.1	1				0
HS10	USB 2.0/1.1	2				0
HS11	USB 2.0/1.1	B1	F3	#17	F_USB	0
HS12	USB 2.0/1.1	B1	F2	#17	F_USB	0
HS13						
HS14	USB Bluetooth (CNVi)					255
SS01	USB 3.1 Gen2	B3	F1	#15	F_USB31C	9
SS02						
SS03	USB 3.1 Gen2	3				3
SS04	USB 3.1 Gen2	4				3
SS05	USB 3.1 Gen1	B2	F4	#16	F_USB30	3
SS06	USB 3.1 Gen1	B2	F5	#16	F_USB30	3
SS07	USB 3.1 Gen1	5				3

April 7, 2019:

HS11 and HS12 are now active in order to support devices connected to F\_USB port on motherboard

USB Connector Types	
0	USB2 Type A
3	USB3 Type A (also for HSxx-ports connected to an USB3 port)
9	USB-C (same SSxx for both connector orientations = internal switch)
10	USB-C (different SSxx for both connector orientations = no internal switch)
255	Other

	Assigned in the SSDT
	Not assigned in the SSDT
	Not supported by the Gigabyte Designare Z390 motherboard