

```

0:100 0:100 MemLog inited, TSC freq: 4008547920
0:100 0:000 MemLog was calibrated without ACPI PM Timer: ACPI I/O
space is not enabled.
0:100 0:000
0:100 0:000 Now is 4.11.2016, 17:19:46 (GMT)
0:100 0:000 Starting Clover revision: 3766 on American Megatrends
EFI
0:100 0:000 Build with: [Args: -x64 -D DISABLE_LTO -t XCODE5 | -D
DISABLE_LTO -D USE_LOW_EBDA -a X64 -b RELEASE -t XCODE5 -n 9 | OS:
10.11.6 | XCODE: 7.3.1]
0:100 0:000
SelfDevicePath=PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x0,0xFFFF,
0x0)\HD(1,GPT,EDAD2EA5-8DE7-4B89-8CF9-10DA31C96A63,0x28,0x64000)
@83733718
0:100 0:000 SelfDirPath = \EFI\BOOT
0:100 0:000 == [ Get Smbios ]
=====
0:100 0:000 Total Memory Slots Count = 4
0:100 0:000 Type 17 Index = 0
0:100 0:000 SmbiosTable.Type17->Speed = 2400MHz
0:100 0:000 SmbiosTable.Type17->Size = 16384MB
0:100 0:000 SmbiosTable.Type17->Bank/Device = BANK 0 ChannelA-DIMM0
0:100 0:000 SmbiosTable.Type17->Vendor = 1315
0:100 0:000 SmbiosTable.Type17->SerialNumber = 11660613
0:100 0:000 SmbiosTable.Type17->PartNumber = BLS16G4D240FSE.16FBD
0:100 0:000 Type 17 Index = 1
0:100 0:000 Ignoring insane frequency value 0MHz
0:100 0:000 SmbiosTable.Type17->Speed = 0MHz
0:100 0:000 SmbiosTable.Type17->Size = 0MB
0:100 0:000 SmbiosTable.Type17->Bank/Device = BANK 1 ChannelA-DIMM1
0:100 0:000 SmbiosTable.Type17->Vendor = <null string>
0:100 0:000 SmbiosTable.Type17->SerialNumber = <null string>
0:100 0:000 SmbiosTable.Type17->PartNumber = <null string>
0:100 0:000 Type 17 Index = 2
0:100 0:000 SmbiosTable.Type17->Speed = 2400MHz
0:100 0:000 SmbiosTable.Type17->Size = 16384MB
0:100 0:000 SmbiosTable.Type17->Bank/Device = BANK 2 ChannelB-DIMM0
0:100 0:000 SmbiosTable.Type17->Vendor = 1315
0:100 0:000 SmbiosTable.Type17->SerialNumber = 11660692
0:100 0:000 SmbiosTable.Type17->PartNumber = BLS16G4D240FSE.16FBD
0:100 0:000 Type 17 Index = 3
0:100 0:000 Ignoring insane frequency value 0MHz
0:100 0:000 SmbiosTable.Type17->Speed = 0MHz
0:100 0:000 SmbiosTable.Type17->Size = 0MB
0:100 0:000 SmbiosTable.Type17->Bank/Device = BANK 3 ChannelB-DIMM1
0:100 0:000 SmbiosTable.Type17->Vendor = <null string>
0:100 0:000 SmbiosTable.Type17->SerialNumber = <null string>
0:100 0:000 SmbiosTable.Type17->PartNumber = <null string>
0:100 0:000 Boot status=0
0:100 0:000 Running on: 'Z170N-Gaming 5' with board 'Z170N-Gaming 5'

```

```

0:100 0:000 === [ GetCPUProperties ]
=====
0:100 0:000 CPU Vendor = 756E6547 Model=506E3
0:100 0:000 got cores from CPUID_1 = 0
0:100 0:000 The CPU supported turbo
0:100 0:000 BrandString = Intel(R) Core(TM) i7-6700K CPU @ 4.00GHz
0:100 0:000 TSC/CCC Information Leaf:
0:100 0:000     numerator      : 334
0:100 0:000     denominator    : 2
0:100 0:000 Calibrated ARTFrequency: 24003280
0:100 0:000 MSR 0xE2 before patch 1E000006
0:100 0:000 MSR 0xE4              00031814
0:100 0:000 MSR 0xCE              00080838_F1012800
0:100 0:000 non-usable FLEX_RATIO = F0000
0:100 0:000 corrected FLEX_RATIO = E0000
0:100 0:000 FSBFrequency=100MHz DMIValue=100000kHz
0:100 0:000 Corrected FSBFrequency=100MHz
0:100 0:000 Vendor/Model/Stepping: 0x756E6547/0x5E/0x3
0:100 0:000 Family/ExtFamily: 0x6/0x0
0:100 0:000 MaxDiv/MinDiv: 40.0/8
0:100 0:000 Turbo: 40/40/40/42
0:100 0:000 Features: 0xBFEBFBFF
0:100 0:000 Threads: 8
0:100 0:000 Cores: 4
0:100 0:000 FSB: 100 MHz
0:100 0:000 CPU: 4000 MHz
0:100 0:000 TSC: 4000 MHz
0:100 0:000 PIS: 400 MHz
0:100 0:000 === [ GetDevices ]
=====
0:100 0:000 PCI (00|00:00.00) : 8086 191F class=060000
0:100 0:000 PCI (00|00:01.00) : 8086 1901 class=060400
0:100 0:000 PCI (00|01:00.00) : 10DE 1402 class=030000
0:100 0:000 - GFX: Model=EVGA GeForce GTX 950 family 126 (Nvidia)
0:100 0:000 PCI (00|01:00.01) : 10DE 0FBA class=040300
0:100 0:000 - HDMI Audio:
0:100 0:000 PCI (00|00:14.00) : 8086 A12F class=0C0330
0:100 0:000 PCI (00|00:14.02) : 8086 A131 class=118000
0:100 0:000 PCI (00|00:16.00) : 8086 A13A class=078000
0:100 0:000 PCI (00|00:17.00) : 8086 A102 class=010601
0:100 0:000 PCI (00|00:1B.00) : 8086 A167 class=060400
0:100 0:000 PCI (00|00:1C.00) : 8086 A110 class=060400
0:100 0:000 PCI (00|03:00.00) : 8086 1578 class=060400
0:100 0:000 PCI (00|04:00.00) : 8086 1578 class=060400
0:100 0:000 PCI (00|04:01.00) : 8086 1578 class=060400
0:100 0:000 PCI (00|04:02.00) : 8086 1578 class=060400
0:100 0:000 PCI (00|07:00.00) : 8086 15B6 class=0C0330
0:100 0:000 PCI (00|04:04.00) : 8086 1578 class=060400
0:100 0:000 PCI (00|00:1C.04) : 8086 A114 class=060400
0:100 0:000 PCI (00|09:00.00) : 1969 E0A1 class=020000

```

```

0:100 0:000 - LAN: 0 Vendor=Atheros
0:100 0:000 PCI (00|00:1C.05) : 8086 A115 class=060400
0:100 0:000 PCI (00|0A:00.00) : 14E4 43B1 class=028000
0:100 0:000 - WIFI: Vendor=Broadcom
0:100 0:000 PCI (00|00:1D.00) : 8086 A118 class=060400
0:100 0:000 PCI (00|00:1D.04) : 8086 A11C class=060400
0:100 0:000 PCI (00|00:1F.00) : 8086 A145 class=060100
0:100 0:000 PCI (00|00:1F.02) : 8086 A121 class=058000
0:100 0:000 PCI (00|00:1F.03) : 8086 A170 class=040300
0:100 0:000 PCI (00|00:1F.04) : 8086 A123 class=0C0500
0:100 0:000 === [ GetDefaultSettings ]
=====
0:100 0:000 Clover load options size = 0 bytes
0:108 0:007 , Status=Success
0:108 0:000 EFI\CLOVER\config.plist loaded: Success
0:108 0:000 === [ GetListOfThemes ]
=====
0:108 0:000 - [00]: embedded
0:108 0:000 - [00]: random
0:109 0:000 - [00]: tonymacx86
0:110 0:001 === [ GetEarlyUserSettings ]
=====
0:110 0:000 timeout set to 3
0:110 0:000 Custom boot CUSTOM_BOOT_DISABLED (0x0)
0:110 0:000 KextsToPatch: 8 requested
0:110 0:000 - [00]: AppleHDA (t1-10.9-10.12-AppleHDA/Realtek
ALC1150) :: BinPatch :: data len: 4
0:110 0:000 - [01]: AppleAHCIPort (External icons patch) ::
BinPatch :: data len: 8
0:110 0:000 - [02]: AirPortBrcm4360 (10.12-BCM94352-5GHz-US-FCC-
dv) :: BinPatch :: data len: 6
0:110 0:000 - [03]: AppleHDA (t1-10.12-AppleHDA/Realtek ALC...) ::
BinPatch :: data len: 4
0:110 0:000 - [04]: AirPortBrcm4360 (AirPortBrcm4360 - fcvo) ::
BinPatch :: data len: 8
0:110 0:000 - [05]: IOBluetoothFamily (10.11-BT4LE-Handoff-Hotspot-
lisai9093) :: BinPatch :: data len: 6
0:110 0:000 - [06]: AppleHDA (t1-AppleHDA/Resources/xml>zml) ::
BinPatch :: data len: 6
0:110 0:000 - [07]: AirPortBrcm4360 (10.11-BCM94352-Airport-
Extreme) :: BinPatch :: data len: 4
0:110 0:000 Default theme: tonymacx86
0:110 0:000 Hiding entries with string Windows
0:110 0:000 Hiding entries with string \EFI\BOOT\BOOTX64.EFI
0:110 0:000 === [ LoadDrivers ]
=====
0:116 0:005 Loading FSInject-64.efi status=Success
0:116 0:000 Loading OsxAptioFix2Drv-64.efi status=Success
0:116 0:000 Loading OsxFatBinaryDrv-64.efi status=Success
0:116 0:000 Loading VBoxHfs-64.efi status=Success

```

```

0:117 0:000 - driver needs connecting
0:117 0:000 1 drivers needs connecting ...
0:117 0:000 PlatformDriverOverrideProtocol->GetDriver overridden
0:117 0:000 Searching for invalid DiskIo BY_DRIVER connects: not
found, all ok
0:455 0:338 Dump SMC keys from NVRAM:
0:465 0:009 === [ InitScreen ]
=====
0:465 0:000 SetScreenResolution: 1920x1080 - not found!
0:465 0:000 SetMaxResolution: found best mode 3: 1280x1024
0:632 0:167 Video mode change to mode #3: Success
0:632 0:000 - set
0:632 0:000 Console modes reported: 4, available modes:
0:632 0:000 - [01]: 80x25 (current mode)
0:632 0:000 - [02]: 80x50
0:632 0:000 - [03]: 100x31
0:632 0:000 - [04]: 128x31
0:632 0:000 reinit: self device
path=PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x0,0xFFFF,
0x0)\HD(1,GPT,EDAD2EA5-8DE7-4B89-8CF9-10DA31C96A63,0x28,0x64000)
1:476 0:843 === [ GetMacAddress ]
=====
1:476 0:000 MAC address of LAN #0= 1C:1B:0D:09:DA:5D:
1:476 0:000 === [ ScanSPD ]
=====
1:476 0:000 SMBus device : 8086 A123 class=0C0500 status=Success
1:476 0:000 SMBus CmdReg: 0x1
1:476 0:000 Scanning SMBus [8086:A123], mmio: 0xDF72A004, ioport:
0xF000, hostc: 0x11
1:476 0:000 Slots to scan [8]...
1:477 0:000 SPD[0]: Type 12 @0x50
1:494 0:017 Unknown vendor bank=0x85 code=0x9B
1:494 0:000 XMP Profile1: 7*125 -42 ns
1:494 0:000 Found module with XMP version 2.0
1:494 0:000 DDR speed 2400MHz
1:494 0:000 Slot: 0 Type 26 16384MB 2400MHz Vendor=NoName
PartNo=BLS16G4D240FSE.16FBD SerialNo=070204020006080A
1:495 0:000 SPD[2]: Type 12 @0x52
1:512 0:017 Unknown vendor bank=0x85 code=0x9B
1:512 0:000 XMP Profile1: 7*125 -42 ns
1:512 0:000 Found module with XMP version 2.0
1:512 0:000 DDR speed 2400MHz
1:512 0:000 Slot: 2 Type 26 16384MB 2400MHz Vendor=NoName
PartNo=BLS16G4D240FSE.16FBD SerialNo=070204020006050C
1:513 0:000 === [ GetAcpiTablesList ]
=====
1:513 0:000 Get Acpi Tables List from RSDT:
1:513 0:000 - [00]: FACP A M I len=132
1:513 0:000 - [01]: APIC A M I len=188
1:513 0:000 - [02]: FPDT A M I len=68

```

```

1:513 0:000 - [03]: FIDT A M I len=156
1:513 0:000 - [04]: MCFG A M I len=60
1:513 0:000 - [05]: HPET A M I len=56
1:513 0:000 - [06]: SSDT SataTabl len=877
1:513 0:000 - [07]: SSDT PerfTune len=1168
1:513 0:000 - [08]: LPIT SKL len=148
1:513 0:000 - [09]: SSDT sensrhub len=584
1:513 0:000 - [10]: SSDT PtidDevc len=11182
1:513 0:000 - [11]: SSDT Ther_Rvp len=3141
1:513 0:000 - [12]: DBGP len=52
1:513 0:000 - [13]: DBG2 len=84
1:513 0:000 - [14]: SSDT xh_rvp10 len=8451
1:513 0:000 - [15]: SSDT SaSsdT len=21380
1:513 0:000 - [16]: UEFI A M I len=66
1:513 0:000 - [17]: SSDT CpuSsdT len=3672
1:513 0:000 - [18]: BGRT ALASKAA len=56
1:513 0:000 - [19]: ASF! HCG len=165
1:513 0:000 Calibrated TSC frequency =4008547920 =4008MHz
1:513 0:000 === [ GetUserSettings ]
=====
1:513 0:000 USB FixOwnership: no
1:513 0:000 - final DSDT Fix mask=00000000
1:513 0:000 PatchesDSDT: 1 requested
1:513 0:000 - [00]: (Rename HDAS to HDEF) lenToFind: 4,
lenToReplace: 4
1:513 0:000 ChassisType: 0xD
1:535 0:021 Using smbios.plist at path: EFI\CLOVER\smbios.plist,
Status=Not Found
1:535 0:000 === [ ScanVolumes ]
=====
1:535 0:000 Found 9 volumes with blockIO
1:535 0:000 - [00]: Volume: PciRoot(0x0)\Pci(0x14,0x0)\USB(0x4,0x3)
1:535 0:000 USB volume
1:535 0:000 - [01]: Volume: PciRoot(0x0)\Pci(0x14,0x0)\USB(0x5,0x0)
1:537 0:001 Result of bootcode detection: bootable unknown
(legacy)
1:537 0:000 USB volume
1:537 0:000 - [02]: Volume:
PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x0,0xFFFF,0x0)
1:537 0:000 - [03]: Volume:
PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x1,0xFFFF,0x0)
1:538 0:000 - [04]: Volume:
PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x0,0xFFFF,
0x0)\HD(1,GPT,EDAD2EA5-8DE7-4B89-8CF9-10DA31C96A63,0x28,0x64000)
1:538 0:000 Result of bootcode detection: bootable unknown
(legacy)
1:538 0:000 This is SelfVolume !!
1:538 0:000 - [05]: Volume:
PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x0,0xFFFF,0x0)\HD(2,GPT,
66568447-313E-42D7-81EA-0FC1D93F93D4,0x64028,0xE8C6E940)

```

```

1:539 0:000 - [06]: Volume:
PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x0,0xFFFF,
0x0)\HD(3,GPT,C1AAB540-43C9-42DE-930C-
CE97CCC45577,0xE8CD2968,0x135F20)
1:540 0:000 - [07]: Volume:
PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x1,0xFFFF,0x0)\HD(1,GPT,
1276CCC1-97BA-46E7-BC09-DC9B2D5C6ACF,0x28,0x64000)
1:540 0:000 Result of bootcode detection: bootable unknown
(legacy)
1:540 0:000 - [08]: Volume:
PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x1,0xFFFF,
0x0)\HD(2,GPT,F2080356-9D69-4943-80BC-CCBE0907DD9B,0x64028,0x74662D60)
1:541 0:000 == [ InitTheme ]
=====
1:541 0:000 Using theme 'tonymacx86' (EFI\CLOVER\themes\tonymacx86)
1:542 0:000 Choosing theme tonymacx86
1:542 0:000 after NVRAM boot-args=dart=0 darkwake=8 kext-dev-mode=1
1:542 0:000 == [ AddCustomLegacy ]
=====
1:542 0:000 Scanning legacy ...
1:542 0:000 0: 'Whole Disc Boot' (legacy) not legacy
1:542 0:000 1: 'Whole Disc Boot' (legacy) not legacy
1:542 0:000 2: 'Whole Disc Boot' (legacy) not legacy
1:542 0:000 3: 'Whole Disc Boot' (legacy) not legacy
1:542 0:000 4: 'EFI' (legacy) not legacy
1:542 0:000 5: 'Enterprise' (legacy) not legacy
1:542 0:000 6: 'Recovery HD' (legacy) not legacy
1:542 0:000 7: 'EFI' (legacy) not legacy
1:542 0:000 8: 'Spare' (legacy) not legacy
1:542 0:000 == [ ScanLoader ]
=====
1:542 0:000 - [04]: 'EFI'
1:542 0:000 - [05]: 'Enterprise'
1:598 0:056 AddLoaderEntry for Volume Name=Enterprise
1:608 0:009 Check if volume Is Hibernated:
1:608 0:000 Check sleep image 'by signature':
1:642 0:034 read prefs
/Library/Preferences/SystemConfiguration/com.apple.PowerManagement.plist
status=Not Found
1:642 0:000 using default sleep image name =
/private/var/vm/sleepimage
1:670 0:028 sleepimage not found -> Not Found
1:670 0:000 hibernated: no - sign
1:677 0:006 - [06]: 'Recovery HD'
1:678 0:001 AddLoaderEntry for Volume Name=Recovery HD
1:704 0:025 - [07]: 'EFI'
1:704 0:000 - [08]: 'Spare'
1:729 0:025 == [ AddCustomTool ]
=====
1:729 0:000 found tool \EFI\CLOVER\tools\Shell64U.efi

```

```

1:729 0:000 Checking EFI partition Volume 4 for Clover
1:729 0:000 Found Clover
1:730 0:001 == [ FindDefaultEntry ]
=====
1:730 0:000 == [ GetEfiBootDeviceFromNvram ]
=====
1:731 0:000 - found entry 0. 'Boot Mac OS X from Enterprise',
Volume 'Enterprise', DevicePath
'PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x0,0xFFFF,0x0)\HD(2,GPT,
66568447-313E-42D7-81EA-0FC1D93F93D4,0x64028,0xE8C6E940)\System\Library\
CoreServices\boot.efi'
1:731 0:000 DefaultIndex=0 and MainMenu.EntryCount=8
1:816 0:085 Found Mouse device:
1:817 0:001 GUI ready
5:880 4:062 == [ StartLoader ]
=====
5:880 0:000 Finally: Bus=100213kHz CPU=4009MHz
5:880 0:000 Loading boot.efi status=Success
6:018 0:137 GetOSVersion: 10.12 (16A323)
6:018 0:000 CSR_CFG: CSR_ALLOW_UNTRUSTED_KEXTS |
CSR_ALLOW_UNRESTRICTED_FS | CSR_ALLOW_TASK_FOR_PID |
CSR_ALLOW_UNRESTRICTED_DTRACE | CSR_ALLOW_UNRESTRICTED_NVRAM
6:018 0:000 Filtering KextPatches:
6:018 0:000 - [00]: AppleHDA (t1-10.9-10.12-AppleHDA/Realtek
ALC1150) :: BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All]
==> allowed
6:018 0:000 - [01]: AppleAHCIPort (External icons patch) ::
BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All] ==> allowed
6:018 0:000 - [02]: AirportBrcm4360 (10.12-BCM94352-5GHz-US-FCC-
dv) :: BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All] ==>
allowed
6:018 0:000 - [03]: AppleHDA (t1-10.12-AppleHDA/Realtek ALC...) ::
BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All] ==> allowed
6:018 0:000 - [04]: AirportBrcm4360 (AirportBrcm4360 - fcvo) ::
BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All] ==> allowed
6:018 0:000 - [05]: IOBluetoothFamily (10.11-BT4LE-Handoff-Hotspot-
lisa9093) :: BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All]
==> allowed
6:018 0:000 - [06]: AppleHDA (t1-AppleHDA/Resources/xml>zml) ::
BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All] ==> allowed
6:018 0:000 - [07]: AirportBrcm4360 (10.11-BCM94352-Airport-
Extreme) :: BinPatch :: [OS: 10.12 | MatchOS: All | MatchBuild: All]
==> allowed
6:018 0:000 == [ PatchSmbios ]
=====
6:018 0:000 insert table 9 for dev 0:0
6:018 0:000 insert table 9 for dev 0:1
6:018 0:000 insert table 9 for dev 0:0
6:018 0:000 insert table 9 for dev 0:0
6:018 0:000 Channels: 2

```

```

6:018 0:000 Interleave: 0 2 1 3 4 6 5 7 8 10 9 11 12 14 13 15 16 18
17 19 20 22 21 23
6:018 0:000 SMBIOS Type 17 Index = 0 => 0 0:
6:018 0:000 BANK0 DIMM0 2400MHz 16384MB
6:018 0:000 SMBIOS Type 17 Index = 1 => 2 2:
6:018 0:000 BANK1 DIMM0 2400MHz 16384MB
6:018 0:000 SMBIOS Type 17 Index = 2 => 1 1:
6:018 0:000 BANK0 DIMM1 EMPTY
6:018 0:000 SMBIOS Type 17 Index = 3 => 3 3:
6:018 0:000 BANK1 DIMM1 EMPTY
6:018 0:000 mTotalSystemMemory = 32768
6:018 0:000 NumberOfMemoryDevices = 4
6:018 0:000 Type20[0]->End = 0xFFFFF, Type17[0] = 0x4000
6:018 0:000 Type20[1]->End = 0x1FFFFFF, Type17[1] = 0xC000
6:018 0:000 Table 131 is present, CPUType=31
6:018 0:000 Change to: 705
6:018 0:000 === [ PatchACPI ]
=====
6:018 0:000 RSDT 0x87F1E028
6:018 0:000 FADT from RSDT: 0x87F1E178
6:018 0:000 XSDT 0x87F1E0A0
6:018 0:000 FADT from XSDT: 0x87F40BD0
6:018 0:000 Xsdt reallocation done
6:018 0:000 old FADT length=10C
6:018 0:000 Apply DsdtFixMask=0x00000000 old way
6:018 0:000 drop _DSM mask=0x0000
6:018 0:000 === [ FixBiosDsdt ]
=====
6:018 0:000 VideoCard devID=0x140210DE
6:018 0:000 DisplayADR1[0] = 0x10000, DisplayADR2[0] = 0x0
6:018 0:000 USBADR[0] = 0x140000 and PCIE = 0xFFFE
6:019 0:000 USBADR[1] = 0x1C0000 and PCIE = 0x0
6:019 0:000 Found Airport BCM at 0x1C0005, 0x0
6:032 0:013 Audio HDA (addr:0x1F0003) setting specified layout-id=1
(0x1)
6:032 0:000 Patching DSDT:
6:032 0:000 - [00]: pattern 48444153, patched at: [ (9C35) (2021)
(86) (D) (A1) (76) ]
6:032 0:000 first CPU found at 862B offset 862E
6:032 0:000 score candidate at 8627
6:032 0:000 score inserted in acpi_cpu_score _PR_
6:032 0:000 Found ACPI CPU: CPU0 | CPU1 | CPU2 | CPU3 | CPU4 | CPU5
| CPU6 | CPU7 , within the score: _PR_
6:033 0:000 Found PCIR00TUID = 0
6:033 0:000 === [ ACPIDropTables ]
=====
6:033 0:000 === [ PatchAllSSDT ]
=====
6:033 0:000 Patch table: SSDT SataTabl
6:033 0:000 SSDT len = 0x36D

```



```

6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Patch table: SSDT PerfTune
6:033 0:000 SSDT len = 0x490
6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Patch table: SSDT sensrhub
6:033 0:000 SSDT len = 0x248
6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Patch table: SSDT PtidDevc
6:033 0:000 SSDT len = 0x2BAE
6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Patch table: SSDT Ther_Rvp
6:033 0:000 SSDT len = 0xC45
6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Patch table: SSDT xh_rvp10
6:033 0:000 SSDT len = 0x2103
6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Patch table: SSDT SaSsdT
6:033 0:000 SSDT len = 0x5384
6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Patch table: SSDT CpuSsdT
6:033 0:000 SSDT len = 0xE58
6:033 0:000 Patching SSDT:
6:033 0:000 - [00]: pattern 48444153, bin not found / already
patched!
6:033 0:000 Drop tables from Xsdt, SIGN=XXXX TableID= Length=0
6:033 0:000 Xsdt has tables count=20
6:033 0:000 corrected XSDT length=196
6:033 0:000 CPUBase=0 and ApicCPUBase=1 ApicCPUNum=1
6:033 0:000 === [ RestSetupOSX ]
=====
6:033 0:000 EdidDiscovered size=128
6:033 0:000 00 | 00 FF FF FF FF FF FF 00 10 AC 5B 40 53 47 42 43
6:033 0:000 16 | 1E 15 01 03 80 26 1E 78 EE EE 95 A3 54 4C 99 26
6:033 0:000 32 | 0F 50 54 A5 4B 00 71 4F 81 80 01 01 01 01 01 01
6:033 0:000 48 | 01 01 01 01 01 01 30 2A 00 98 51 00 2A 40 30 70
6:033 0:000 64 | 13 00 78 2D 11 00 00 1E 00 00 00 FF 00 4D 33 39

```

```
6:033 0:000 80 | 4D 44 31 37 55 43 42 47 53 0A 00 00 00 FC 00 44
6:033 0:000 96 | 45 4C 4C 20 50 31 39 30 53 0A 20 20 00 00 00 FD
6:033 0:000 112 | 00 38 4C 1E 51 0E 00 0A 20 20 20 20 20 20 00 4B
6:033 0:000 NVidia GFX injection not set
6:033 0:000 RCBA disabled; cannot use it
6:033 0:000 HDA Controller [8086:A170] :: PciRoot(0x0)\Pci(0x1F,0x3)
=> setting specified layout-id=1 (0x1)
6:033 0:000 stringlength = 552
6:033 0:000 CurrentMode: Width=1280 Height=1024
6:033 0:000 Beginning FSInjection
FSInjectionInstall ...
- Our FSI_SIMPLE_FILE_SYSTEM_PROTOCOL installed on handle: 83733498
FSInjectionInstall ...
- Our FSI_SIMPLE_FILE_SYSTEM_PROTOCOL installed on handle: 83733498
6:034 0:000 ** Warning: Your MLB is not suitable for iMessage(must
be 17 chars long) !
6:040 0:006 Preparing kexts injection for arch=x86_64 from
EFI\CLOVER\kexts\Other
6:040 0:000 Extra kext: EFI\CLOVER\kexts\Other\realtekALC.kext
6:045 0:005 Custom boot is disabled
```