


Atheros WiFi fix for Mojave

***Credits to Tonymacx86 for kextbeast and others for finding the Atheros40kext compatibility in Mojave. This is not my idea but just a simple way to fix Atheros WiFi in Mojave. This is not meant to be used on any other forum other than Tonymacx86 so please don't repost it at other sites or give to non members from this site.

Atheros WiFi Fix for Mojave. Atheros WiFi has been dropped from Mojave but there is a fix using the High Sierra Atheros40kext and adding it to either Library/extensions folder, or if that doesn't work then adding it to System/Library/extensions folder. Using Kextbeast this is easily done and it will repair permissions and rebuild caches. This fix may not work for all Atheros WiFi modules but it has worked for common natively compatible Atheros modules that worked in previous macOS software versions.


Plan A

Place only the Atheros40kext on your desktop (make sure no other kexts are there) run Kextbeast and select library/Extensions as destination target. See pic below. Reboot and check for WiFi. If it doesn't show any hardware on top tool bar then go to Plan B.



Plan B

Place the IO80211Familykext on your desktop (make sure no other kexts are there) run Kextbeast and select System/Library/Extensions as destination target. See pic below.



KextBeast.

- Introduction
- License
- Destination Select
- **Installation Type**
- Installation
- Summary



Custom Install on "Mojave 2"

| Package Name | Action | Size |
|--|---------|---------|
| <input type="checkbox"/> /Library/Extensions | Skip | Zero KB |
| <input checked="" type="checkbox"/> /System/Library/Extensions | Upgrade | Zero KB |

Space Required: Zero KB

Remaining: 94.54 GB

Choose this to install to /System/Library Extensions.

Go Back

Continue

2018-10...8:46 PM

2018-11...18.