

0:100 0:100 MemLog inited, TSC freq: 4200570420  
0:100 0:000 MemLog was calibrated without ACPI PM Timer: ACPI I/O space is not enabled.  
0:100 0:000  
0:100 0:000 Now is 9.4.2017, 7:47:55 (GMT)  
0:100 0:000 Starting Clover revision: 3766 on American Megatrends EFI  
0:100 0:000 Build with: [Args: -x64 -D DISABLE\_LTO -t XCODE5 I -D DISABLE\_LTO -D USE\_LOW\_EBDA -a X64 -b RELEASE -t XCODE5 -n 9 I OS: 10.11.6 I XCODE: 7.3.1]  
0:100 0:000 SelfDevicePath=PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x3,0xFFFF,0x0)\HD(1,GPT,23804F31-E26C-49F2-B58C-1139DECEB3FE,0x28,0x64000)@C5C7DF18  
0:100 0:000 SelfDirPath = \EFI\BOOT  
0:103 0:002 === [ Get Smbios ] =====  
0:103 0:000 Total Memory Slots Count = 4  
0:103 0:000 Type 17 Index = 0  
0:103 0:000 SmbiosTable.Type17->Speed = 2400MHz  
0:103 0:000 SmbiosTable.Type17->Size = 8192MB  
0:103 0:000 SmbiosTable.Type17->Bank/Device = BANK 0 ChannelA-DIMM0  
0:103 0:000 SmbiosTable.Type17->Vendor = Kingston  
0:103 0:000 SmbiosTable.Type17->SerialNumber = 31168A8A  
0:103 0:000 SmbiosTable.Type17->PartNumber = KHX2400C15/8G  
0:103 0:000 Type 17 Index = 1  
0:103 0:000 Ignoring insane frequency value 0MHz  
0:103 0:000 SmbiosTable.Type17->Speed = 0MHz  
0:103 0:000 SmbiosTable.Type17->Size = 0MB  
0:103 0:000 SmbiosTable.Type17->Bank/Device = BANK 1 ChannelA-DIMM1  
0:103 0:000 SmbiosTable.Type17->Vendor = <null string>  
0:103 0:000 SmbiosTable.Type17->SerialNumber = <null string>  
0:103 0:000 SmbiosTable.Type17->PartNumber = <null string>  
0:103 0:000 Type 17 Index = 2  
0:103 0:000 SmbiosTable.Type17->Speed = 2400MHz  
0:103 0:000 SmbiosTable.Type17->Size = 8192MB  
0:103 0:000 SmbiosTable.Type17->Bank/Device = BANK 2 ChannelB-DIMM0  
0:103 0:000 SmbiosTable.Type17->Vendor = Kingston  
0:103 0:000 SmbiosTable.Type17->SerialNumber = 061653C9  
0:103 0:000 SmbiosTable.Type17->PartNumber = KHX2400C15/8G  
0:103 0:000 Type 17 Index = 3  
0:103 0:000 Ignoring insane frequency value 0MHz  
0:103 0:000 SmbiosTable.Type17->Speed = 0MHz  
0:103 0:000 SmbiosTable.Type17->Size = 0MB  
0:103 0:000 SmbiosTable.Type17->Bank/Device = BANK 3 ChannelB-DIMM1  
0:103 0:000 SmbiosTable.Type17->Vendor = <null string>  
0:103 0:000 SmbiosTable.Type17->SerialNumber = <null string>  
0:103 0:000 SmbiosTable.Type17->PartNumber = <null string>  
0:103 0:000 Boot status=0  
0:103 0:000 Running on: 'Z270-HD3P' with board 'Z270-HD3P-CF'

```
0:103 0:000 === [ GetCPUProperties ] =====
0:103 0:000 CPU Vendor = 756E6547 Model=906E9
0:103 0:000 got cores from CUID_1 = 0
0:103 0:000 The CPU supported turbo
0:103 0:000 BrandString = Intel(R) Core(TM) i7-7700K CPU @ 4.20GHz
0:103 0:000 TSC/CCC Information Leaf:
0:103 0:000   numerator   : 350
0:103 0:000   denominator : 2
0:103 0:000 Calibrated ARTFrequency: 24003259
0:103 0:000 FSBFrequency=100MHz DMIvalue=100000kHz
0:103 0:000 Corrected FSBFrequency=100MHz
0:103 0:000 Vendor/Model/Stepping: 0x756E6547/0x9E/0x9
0:103 0:000 Family/ExtFamily: 0x6/0x0
0:103 0:000 MaxDiv/MinDiv: 45.0/6
0:103 0:000 Turbo: 0/0/0/0
0:103 0:000 Features: 0xBFEBFBFF
0:103 0:000 Threads: 16
0:103 0:000 Cores: 1
0:103 0:000 FSB: 100 MHz
0:103 0:000 CPU: 4500 MHz
0:103 0:000 TSC: 4500 MHz
0:103 0:000 PIS: 400 MHz
0:103 0:000 === [ GetDevices ] =====
0:103 0:000 PCI (00100:00.00) : 8086 591F class=060000
0:103 0:000 PCI (00100:02.00) : 8086 5912 class=030000
0:103 0:000 - GFX: Model=Intel Unknown (Intel)
0:103 0:000 PCI (00100:08.00) : 8086 1911 class=088000
0:103 0:000 PCI (00100:14.00) : 8086 A2AF class=0C0330
0:103 0:000 PCI (00100:16.00) : 8086 A2BA class=078000
0:103 0:000 PCI (00100:17.00) : 8086 A282 class=010601
0:103 0:000 PCI (00100:1B.00) : 8086 A2E7 class=060400
0:103 0:000 PCI (00100:1B.02) : 8086 A2E9 class=060400
0:103 0:000 PCI (00102:00.00) : 1283 8892 class=060401
0:103 0:000 PCI (00100:1B.03) : 8086 A2EA class=060400
0:103 0:000 PCI (00100:1B.04) : 8086 A2EB class=060400
0:103 0:000 PCI (00100:1C.00) : 8086 A290 class=060400
0:103 0:000 PCI (00100:1C.04) : 8086 A294 class=060400
0:103 0:000 PCI (00107:00.00) : 1B21 2142 class=0C0330
0:103 0:000 PCI (00100:1C.06) : 8086 A296 class=060400
0:103 0:000 PCI (00100:1D.00) : 8086 A298 class=060400
0:103 0:000 PCI (00100:1F.00) : 8086 A2C5 class=060100
0:103 0:000 PCI (00100:1F.02) : 8086 A2A1 class=058000
0:103 0:000 PCI (00100:1F.03) : 8086 A2F0 class=040300
0:103 0:000 PCI (00100:1F.04) : 8086 A2A3 class=0C0500
0:103 0:000 PCI (00100:1F.06) : 8086 15B8 class=020000
0:103 0:000 - LAN: 0 Vendor=Intel
0:103 0:000 === [ GetDefaultSettings ] =====
```

```

0:103 0:000 Clover load options size = 0 bytes
0:109 0:005 , Status=Success
0:109 0:000 EFI\CLOVER\config.plist loaded: Success
0:109 0:000 === [ GetListOfThemes ] =====
0:109 0:000 - [00]: embedded
0:113 0:003 - [00]: random
0:115 0:002 - [00]: tonymacx86
0:120 0:004 === [ GetEarlyUserSettings ] =====
0:120 0:000 timeout set to 3
0:120 0:000 Custom boot CUSTOM_BOOT_DISABLED (0x0)
0:120 0:000 FakeCPUID: 506E3
0:120 0:000 KextsToPatch: 5 requested
0:120 0:000 - [00]: AppleAHCIPort (External icons patch) :: BinPatch :: data len: 8
0:120 0:000 - [01]: AppleIntelSKLGraphicsFramebuffer (10.11-
SKL-1912000-4_displays) :: BinPatch :: data len: 4
0:120 0:000 - [02]: AppleHDA (10.12-AppleHDA/Realtek ALC...) :: BinPatch :: data len:
4
0:120 0:000 - [03]: AppleHDA (10.9-10.12-AppleHDA/Realtek ALC887) :: BinPatch ::
data len: 4
0:120 0:000 - [04]: AppleHDA (AppleHDA/Resources/xml>zml) :: BinPatch :: data len:
6
0:120 0:000 Default theme: tonymacx86
0:120 0:000 Hiding entries with string Windows
0:120 0:000 Hiding entries with string \EFI\BOOT\BOOTX64.EFI
0:120 0:000 === [ LoadDrivers ] =====
0:121 0:001 Loading FSInject-64.efi status=Success
0:127 0:006 Loading OsxAptioFix2Drv-64.efi status=Success
0:131 0:004 Loading OsxFatBinaryDrv-64.efi status=Success
0:136 0:004 Loading VBoxHfs-64.efi status=Success
0:140 0:004 - driver needs connecting
0:141 0:000 1 drivers needs connecting ...
0:141 0:000 PlatformDriverOverrideProtocol->GetDriver overriden
0:141 0:000 Searching for invalid DiskIo BY_DRIVER connects: not found, all ok
0:270 0:129 Dump SMC keys from NVRAM:
0:290 0:020 fakesmc-key-#KEY-ui32:00 00 00 11
0:291 0:000 fakesmc-key-$Adr-ui32:00 00 03 00
0:292 0:000 fakesmc-key-$Num-ui8:01
0:292 0:000 fakesmc-key-RMde-char:41
0:295 0:002 fakesmc-key-RPlt-ch8*:6A 31 37 00 00 00 00 00
0:296 0:000 fakesmc-key-RBr -ch8*:6A 31 36 6A 31 37 00 00
0:296 0:000 fakesmc-key-EPCL-ui32:07 A0 07 00
0:297 0:000 fakesmc-key-REV -ch8*:02 15 0F 00 00 07
0:298 0:000 fakesmc-key-BEMB-flag:00
0:299 0:000 fakesmc-key-BATP-flag:00
0:299 0:000 fakesmc-key-BNum-ui8:00
0:300 0:000 fakesmc-key-MSTC-ui8:00
0:301 0:000 fakesmc-key-MSAc-ui16:00 00

```

```

0:302 0:000 fakesmc-key-MSLD-ui8:00
0:302 0:000 fakesmc-key-MSWr-ui8:00
0:303 0:000 fakesmc-key-MSFW-ui8:01 00
0:304 0:000 fakesmc-key-MSPS-ui16:00 03
0:321 0:017 === [ InitScreen ] =====
0:321 0:000 SetScreenResolution: 1920x1080 - not found!
0:321 0:000 SetMaxResolution: found best mode 5: 2560x1440
0:573 0:252 Video mode change to mode #5: Success
0:573 0:000 - set
0:573 0:000 Console modes reported: 5, available modes:
0:573 0:000 - [01]: 80x25
0:573 0:000 - [02]: 80x50
0:573 0:000 - [03]: 100x31
0:573 0:000 - [04]: 127x33 (current mode)
0:573 0:000 - [05]: 100x60
0:573 0:000 SetScreenResolution: 2560x1440 - already set
0:573 0:000 reinit: self device path=PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x3,0xFFFF,
0x0)\HD(1,GPT,23804F31-E26C-49F2-B58C-1139DECEB3FE,0x28,0x64000)
0:577 0:003 === [ GetMacAddress ] =====
0:577 0:000 === [ ScanSPD ] =====
0:577 0:000 SMBus device : 8086 A2A3 class=0C0500 status=Success
0:577 0:000 SMBus CmdReg: 0x1
0:577 0:000 Scanning SMBus [8086:A2A3], mmio: 0xF714A004, ioport: 0xF040, hostc:
0x11
0:577 0:000 Slots to scan [8]...
0:578 0:000 SPD[0]: Type 12 @0x50
0:596 0:017 XMP Profile1: 7*125 -42 ns
0:596 0:000 Found module with XMP version 2.0
0:596 0:000 DDR speed 2400MHz
0:596 0:000 Slot: 0 Type 26 8192MB 2400MHz Vendor=Kingston
PartNo=KHX2400C158G SerialNo=03010106080A080A
0:596 0:000 SPD[2]: Type 12 @0x52
0:614 0:017 XMP Profile1: 7*125 -42 ns
0:614 0:000 Found module with XMP version 2.0
0:614 0:000 DDR speed 2400MHz
0:614 0:000 Slot: 2 Type 26 8192MB 2400MHz Vendor=Kingston
PartNo=KHX2400C158G SerialNo=0006010605030C09
0:615 0:000 === [ GetAcpiTablesList ] =====
0:615 0:000 Get Acpi Tables List from RSDT:
0:615 0:000 - [00]: FACP A M I len=132
0:615 0:000 - [01]: APIC A M I len=188
0:615 0:000 - [02]: FPDT A M I len=68
0:615 0:000 - [03]: MCFG A M I len=60
0:615 0:000 - [04]: SSDT SataTabl len=956
0:615 0:000 - [05]: FIDT A M I len=156
0:615 0:000 - [06]: SSDT SaSsdtd len=12633
0:615 0:000 - [07]: SSDT PegSsdtd len=9567

```

```

0:615 0:000 - [08]: HPET KBL len=56
0:615 0:000 - [09]: SSDT Ther_Rvp len=3557
0:615 0:000 - [10]: SSDT xh_rvp10 len=10967
0:615 0:000 - [11]: UEFI EDK2 len=66
0:615 0:000 - [12]: SSDT CpuSsdT len=3806
0:615 0:000 - [13]: LPIT KBL len=148
0:615 0:000 - [14]: WSMT KBL len=40
0:615 0:000 - [15]: SSDT sensrhub len=671
0:615 0:000 - [16]: SSDT PtidDevc len=12290
0:615 0:000 - [17]: DBGP len=52
0:615 0:000 - [18]: DBG2 len=84
0:615 0:000 - [19]: BGRT A M I len=56
0:615 0:000 Calibrated TSC frequency =4200570420 =4200MHz
0:615 0:000 === [ GetUserSettings ] =====
0:615 0:000 Add 1 properties:
0:615 0:000 - [00]: IntelGFX, len: 4
0:615 0:000 USB FixOwnership: no
0:615 0:000 - final DSDT Fix mask=00000000
0:615 0:000 ChassisType: 0xD
0:618 0:002 Using smbios.plist at path: EFI\CLOVER\smbios.plist, Status=Not Found
0:619 0:001 === [ ScanVolumes ] =====
0:619 0:000 Found 12 volumes with blockIO
0:619 0:000 - [00]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x3,0xFFFF,0x0)
0:620 0:000 - [01]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x4,0xFFFF,0x0)
0:622 0:002 - [02]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x5,0xFFFF,0x0)
0:622 0:000 Result of bootcode detection: bootable unknown (legacy)
0:622 0:000 - [03]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x3,0xFFFF,
0x0)\HD(1,GPT,23804F31-E26C-49F2-B58C-1139DECEB3FE,0x28,0x64000)
0:623 0:000 Result of bootcode detection: bootable unknown (legacy)
0:624 0:001 This is SelfVolume !!
0:624 0:000 - [04]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x3,0xFFFF,
0x0)\HD(2,GPT,BF4813F6-3CA4-4EA5-A9A8-FD9FF9548ADE,0x64028,0xDDFAC40)
0:625 0:000 - [05]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x3,0xFFFF,
0x0)\HD(3,GPT,C29FEF16-F1F4-4E09-91F2-EA6CDCB99279,0xDE5EC68,0x135F20)
0:626 0:000 - [06]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x4,0xFFFF,
0x0)\HD(1,GPT,8E65C3EA-C71C-4472-B41F-BD43956F5DC1,0x800,0xE1000)
0:626 0:000 Result of bootcode detection: bootable Windows (vista,win)
0:626 0:000 - [07]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x4,0xFFFF,
0x0)\HD(2,GPT,957C32DB-2D2E-4146-8E3F-C0B286C4A2D5,0xE1800,0x32000)
0:627 0:000 Result of bootcode detection: bootable Windows (vista,win)
0:629 0:001 - [08]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x4,0xFFFF,
0x0)\HD(3,GPT,6BFA0605-EDEA-471A-99AB-AA416220F85C,0x113800,0x8000)
0:629 0:000 - [09]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x4,0xFFFF,
0x0)\HD(4,GPT,620D9A38-1C7C-4A37-A4E1-82B935585D2E,0x11B800,0x1D0AA000)
0:630 0:000 Result of bootcode detection: bootable Windows (vista,win)
0:630 0:000 - [10]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x5,0xFFFF,
0x0)\HD(1,GPT,62EA6A53-AB06-4DEE-AA99-F18FC6D0DF4C,0x22,0x40000)

```

```

0:630 0:000 - [11]: Volume: PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x5,0xFFFF,
0x0)\HD(2,GPT,8DF1A786-5801-497B-AFB7-675ADD9E7249,0x40800,0x746C6000)
0:631 0:000      Result of bootcode detection: bootable Windows (vista,win)
0:631 0:000 === [ InitTheme ] =====
0:634 0:003 Using theme 'tonymacx86' (EFI\CLOVER\themes\tonymacx86)
0:636 0:001 Choosing theme tonymacx86
0:636 0:000 after NVRAM boot-args=dart=0 kext-dev-mode=1
0:636 0:000 === [ AddCustomLegacy ] =====
0:636 0:000 Scanning legacy ...
0:636 0:000 0: 'Whole Disc Boot' (legacy) not legacy
0:636 0:000 1: 'Whole Disc Boot' (legacy) not legacy
0:636 0:000 2: 'Whole Disc Boot' (legacy) not legacy
0:636 0:000 3: 'EFI' (legacy) not legacy
0:636 0:000 4: 'MacOS Sierra' (legacy) not legacy
0:636 0:000 5: 'Recovery HD' (legacy) not legacy
0:636 0:000 6: 'Legacy HD1' (vista,win) add legacy
0:647 0:010 added 'Boot Windows from Legacy HD1' OStype=2 Icon=vista,win
0:647 0:000 7: 'EFI' (vista,win) add legacy
0:650 0:003 added 'Boot Windows from EFI' OStype=2 Icon=vista,win
0:650 0:000 8: 'Legacy HD3' (legacy) not legacy
0:650 0:000 9: 'Legacy HD4' (vista,win) add legacy
0:654 0:003 added 'Boot Windows from Legacy HD4' OStype=2 Icon=vista,win
0:654 0:000 10: 'Legacy HD1' (legacy) not legacy
0:654 0:000 11: 'Legacy HD2' (vista,win) add legacy
0:657 0:003 added 'Boot Windows from Legacy HD2' OStype=2 Icon=vista,win
0:657 0:000 === [ ScanLoader ] =====
0:657 0:000 - [03]: 'EFI'
0:713 0:056 - [04]: 'MacOS Sierra'
0:720 0:006      AddLoaderEntry for Volume Name=MacOS Sierra
0:721 0:001      Check if volume Is Hibernated:
0:721 0:000      Check sleep image 'by signature':
0:728 0:006      read prefs
/Library/Preferences/SystemConfiguration/com.apple.PowerManagement.plist
status=Not Found
0:728 0:000      using default sleep image name = \private\var\vm\sleepimage
0:733 0:004      sleepimage not found -> Not Found
0:733 0:000      hibernated: no - sign
0:778 0:045 - [05]: 'Recovery HD'
0:780 0:001      AddLoaderEntry for Volume Name=Recovery HD
0:825 0:045 - [07]: 'EFI'
0:837 0:011      AddLoaderEntry for Volume Name=EFI
0:888 0:051 === [ AddCustomTool ] =====
0:892 0:003 found tool \EFI\CLOVER\tools\Shell64U.efi
0:892 0:000 Checking EFI partition Volume 3 for Clover
0:895 0:003 Found Clover
0:908 0:012 === [ FindDefaultEntry ] =====
0:908 0:000 === [ GetEfiBootDeviceFromNvram ] =====

```

```

0:908 0:000 - found entry 4. 'Boot Mac OS X from MacOS Sierra', Volume 'MacOS
Sierra', DevicePath 'PciRoot(0x0)\Pci(0x17,0x0)\Sata(0x3,0xFFFF,
0x0)\HD(2,GPT,BF4813F6-3CA4-4EA5-A9A8-FD9FF9548ADE,
0x64028,0xDDFAC40)\System\Library\CoreServices\boot.efi'
0:908 0:000 DefaultIndex=4 and MainMenu.EntryCount=13
1:073 0:165 Found Mouse device:
1:078 0:004 GUI ready
1:690 0:612 BootOption of the entry is empty
1:690 0:000 === [ StartLoader ] =====
1:690 0:000 Finally: Bus=93346kHz CPU=4201MHz
1:690 0:000 Loading boot.efi status=Success
1:870 0:179 GetOSVersion: 10.12.4 (16E195)
1:870 0:000 CSR_CFG: CSR_ALLOW_UNTRUSTED_KEXTS I
CSR_ALLOW_UNRESTRICTED_FS
1:870 0:000 Filtering KextPatches:
1:870 0:000 - [00]: AppleAHCIPort (External icons patch) :: BinPatch :: [OS: 10.12.4 I
MatchOS: All I MatchBuild: All] ==> allowed
1:870 0:000 - [01]: AppleIntelSKLGraphicsFramebuffer (10.11-
SKL-1912000-4_displays) :: BinPatch :: [OS: 10.12.4 I MatchOS: All I MatchBuild: All]
==> allowed
1:870 0:000 - [02]: AppleHDA (10.12-AppleHDA/Realtek ALC...) :: BinPatch :: [OS:
10.12.4 I MatchOS: All I MatchBuild: All] ==> allowed
1:870 0:000 - [03]: AppleHDA (10.9-10.12-AppleHDA/Realtek ALC887) :: BinPatch ::
[OS: 10.12.4 I MatchOS: All I MatchBuild: All] ==> allowed
1:870 0:000 - [04]: AppleHDA (AppleHDA/Resources/xml>zml) :: BinPatch :: [OS:
10.12.4 I MatchOS: All I MatchBuild: All] ==> allowed
1:870 0:000 === [ PatchSmbios ] =====
1:870 0:000 insert table 9 for dev 1F:6
1:870 0:000 Channels: 2
1:870 0:000 Interleave: 0 2 1 3 4 6 5 7 8 10 9 11 12 14 13 15 16 18 17 19 20 22 21 23
1:870 0:000 SMBIOS Type 17 Index = 0 => 0 0:
1:870 0:000 BANK0 DIMM0 2400MHz 8192MB
1:870 0:000 SMBIOS Type 17 Index = 1 => 2 2:
1:870 0:000 BANK1 DIMM0 2400MHz 8192MB
1:870 0:000 SMBIOS Type 17 Index = 2 => 1 1:
1:870 0:000 BANK0 DIMM1 EMPTY
1:870 0:000 SMBIOS Type 17 Index = 3 => 3 3:
1:870 0:000 BANK1 DIMM1 EMPTY
1:870 0:000 mTotalSystemMemory = 16384
1:870 0:000 NumberOfMemoryDevices = 4
1:870 0:000 Type20[0]->End = 0x7FFFFFFF, Type17[0] = 0x2000
1:870 0:000 Type20[1]->End = 0xFFFFFFFF, Type17[1] = 0x6000
1:870 0:000 Table 131 is present, CPUType=31
1:870 0:000 Change to: 402
1:870 0:000 === [ PatchACPI ] =====
1:870 0:000 RSDT 0xCA115028
1:870 0:000 FADT from RSDT: 0xCA115178

```

```

1:870 0:000 XSDT 0xCA1150A0
1:870 0:000 FADT from XSDT: 0xCA13C170
1:870 0:000 Xsdt reallocation done
1:870 0:000 old FADT length=114
1:872 0:002 Apply DsdtFixMask=0x00000000 old way
1:872 0:000 drop _DSM mask=0x0000
1:872 0:000 === [ FixBiosDsdt ] =====
1:872 0:000 VideoCard devID=0x59128086
1:872 0:000 DisplayADR1[0] = 0x20000, DisplayADR2[0] = 0xFFFFE
1:872 0:000 USBADR[0] = 0x140000 and PCIe = 0xFFFFE
1:873 0:000 USBADR[1] = 0x1C0004 and PCIe = 0x0
1:873 0:000 Audio HDA (addr:0x1F0003) setting specified layout-id=1 (0x1)
1:873 0:000 first CPU found at A184 offset A187
1:873 0:000 score candidate at A180
1:873 0:000 score inserted in acpi_cpu_score _PR_
1:873 0:000 Found ACPI CPU: CPU0 | CPU1 | CPU2 | CPU3 | CPU4 | CPU5 | CPU6 |
CPU7 , within the score: _PR_
1:873 0:000 Found PCIROOTUID = 0
1:873 0:000 === [ ACPIDropTables ] =====
1:873 0:000 === [ PatchAllSSDT ] =====
1:873 0:000 Patch table: SSDT SataTabl
1:873 0:000 SSDT len = 0x3BC
1:873 0:000 Patch table: SSDT SaSsdt
1:873 0:000 SSDT len = 0x3159
1:873 0:000 Patch table: SSDT PegSsdt
1:873 0:000 SSDT len = 0x255F
1:873 0:000 Patch table: SSDT Ther_Rvp
1:873 0:000 SSDT len = 0xDE5
1:873 0:000 Patch table: SSDT xh_rvp10
1:873 0:000 SSDT len = 0x2AD7
1:873 0:000 Patch table: SSDT CpuSsdt
1:873 0:000 SSDT len = 0xEDE
1:873 0:000 Patch table: SSDT sensrhub
1:873 0:000 SSDT len = 0x29F
1:873 0:000 Patch table: SSDT PtidDevc
1:873 0:000 SSDT len = 0x3002
1:873 0:000 Drop tables from Xsdt, SIGN=XXXX TableID= Length=0
1:873 0:000 Xsdt has tables count=20
1:873 0:000 corrected XSDT length=196
1:873 0:000 CPUBase=0 and ApicCPUBase=1 ApicCPUNum=1
1:873 0:000 === [ RestSetupOSX ] =====
1:873 0:000 EdidDiscovered size=128
1:873 0:000 00 | 00 FF FF FF FF FF FF 00 10 AC 69 D0 4C 45 54 30
1:873 0:000 16 | 16 1A 01 03 80 3C 22 78 EE 44 55 A9 55 4D 9D 26
1:873 0:000 32 | 0F 50 54 A5 4B 00 B3 00 D1 00 71 4F A9 40 81 80
1:873 0:000 48 | 77 80 01 01 01 01 56 5E 00 A0 A0 A0 29 50 30 20
1:873 0:000 64 | 35 00 55 50 21 00 00 1A 00 00 00 FF 00 47 48 38

```



1:873 0:000 80 | 35 44 36 36 35 30 54 45 4C 0A 00 00 00 FC 00 44  
1:873 0:000 96 | 45 4C 4C 20 55 32 37 31 35 48 0A 20 00 00 00 FD  
1:873 0:000 112 | 00 38 56 1E 71 1E 00 0A 20 20 20 20 20 20 01 CA  
1:873 0:000 Intel Intel Unknown [8086:5912] :: PciRoot(0x0)\Pci(0x2,0x0)  
1:873 0:000 custom IntelGFX properties injected, continue  
1:873 0:000 Intel card id=5912 unsupported, please report to the project home  
1:873 0:000 Intel GFX revision =0x4  
1:873 0:000 RCBA disabled; cannot use it  
1:873 0:000 HDA Controller [8086:A2F0] :: PciRoot(0x0)\Pci(0x1F,0x3) => setting  
specified layout-id=1 (0x1)  
1:874 0:000 stringlength = 1310  
1:874 0:000 CurrentMode: Width=2560 Height=1440  
1:874 0:000 Beginning FSInjection  
FSInjectionInstall ...  
- Our FSI\_SIMPLE\_FILE\_SYSTEM\_PROTOCOL installed on handle: C5C7D798  
FSInjectionInstall ...  
- Our FSI\_SIMPLE\_FILE\_SYSTEM\_PROTOCOL installed on handle: C5C7D798  
1:888 0:014 Preparing kexts injection for arch=x86\_64 from EFI\CLOVER\kexts\Other  
1:890 0:002 Preparing kexts injection for arch=x86\_64 from EFI\CLOVER\kexts\10.12  
1:893 0:002 Custom boot is disabled