

0:100 0:100 MemLog inited, TSC freq: 3092976240  
0:100 0:000 LegacyRegion2: Chipset/proc: 0x01508086  
0:100 0:000 Next Generation Core processors (PAM 0x80-0x86)  
0:100 0:000 Test PAM1=(0x41=90, 0x5a=90, 0x81=11, 0x91=00) at chipset  
01508086  
0:100 0:000 , Install = Success  
0:112 0:012 BiosVideoDriverBindingStart!  
0:112 0:000 BiosVideoCheckForVbe  
0:112 0:000 EdidOverride not found  
0:256 0:143 Edid1-  
0:400 0:143 Edid0-  
0:426 0:026 0 640x480 attr=3BF - ok, 640x480, working, highest, pref=0  
0:427 0:001 1 800x600 attr=3BF - ok, 800x600, working, highest, pref=1  
0:428 0:001 2 1024x768 attr=3BF - ok, 1024x768, working, highest, pref=2  
0:433 0:004 BV new mode: 2 1024x768  
0:576 0:142 SetMode pref 2 (2) = Success  
4:784 4:208  
4:784 0:000 Now is 19.11.2015, 17:10:11 (GMT+2047)  
4:784 0:000 Starting Clover rev 3270 on CLOVER EFI  
4:784 0:000 SelfDevicePath=PcieRoot(0x0)\Pci(0x1F,  
0x2)\Sata(0x1,0x0,0x0)\HD(1,GPT,7460A46D-6F4E-4AED-A1B6-E20225C09D7B,  
0x28,0x64000) @1F47CD98  
4:784 0:000 SelfDirPath = \EFI\CLOVER  
4:784 0:000 Total Memory Slots Count = 2  
4:784 0:000 Type 17 Index = 0  
4:784 0:000 SmbiosTable.Type17->Speed = 1600MHz  
4:784 0:000 SmbiosTable.Type17->Size = 4096MB  
4:784 0:000 SmbiosTable.Type17->Bank/Device = BANK 0 ChannelA-DIMM0  
4:784 0:000 Type 17 Index = 1  
4:784 0:000 SmbiosTable.Type17->Speed = 1600MHz  
4:784 0:000 SmbiosTable.Type17->Size = 2048MB  
4:784 0:000 SmbiosTable.Type17->Bank/Device = BANK 2 ChannelB-DIMM0  
4:784 0:000 Boot status=0  
4:784 0:000 Clover revision: 3270 running on To Be Filled By O.E.M.  
4:784 0:000 ... with board H61M-ITX  
4:784 0:000 CPU Vendor = 756E6547 Model=306A9  
4:784 0:000 The CPU not supported turbo  
4:784 0:000 BrandString = Intel(R) Pentium(R) CPU G2120 @ 3.10GHz  
4:784 0:000 MSR 0xE2 before patch 1E000400  
4:784 0:000 MSR 0xE4 00010414  
4:784 0:000 MSR 0xCE 00081010\_E0011F00  
4:784 0:000 non-usable FLEX\_RATIO = 10000  
4:784 0:000 corrected FLEX\_RATIO = 0  
4:784 0:000 MSR 0x1B0 00000000  
4:784 0:000 FSBFrequency=100MHz DMIvalue=100000kHz  
4:784 0:000 Corrected FSBFrequency=100MHz  
4:784 0:000 Vendor/Model/Stepping: 0x756E6547/0x3A/0x9  
4:784 0:000 Family/ExtFamily: 0x6/0x0  
4:784 0:000 MaxDiv/MinDiv: 31.0/16  
4:784 0:000 Turbo: 31/31/31/31

4:784 0:000 Features: 0xBFEBFBFF  
4:784 0:000 Threads: 2  
4:784 0:000 Cores: 2  
4:784 0:000 FSB: 100 MHz  
4:784 0:000 CPU: 3100 MHz  
4:784 0:000 TSC: 3100 MHz  
4:784 0:000 PIS: 400 MHz  
4:784 0:000 PCI (00100:00.00) : 8086 0150 class=060000  
4:784 0:000 PCI (00100:01.00) : 8086 0151 class=060400  
4:784 0:000 PCI (00101:00.00) : 10DE 10C3 class=030000  
4:784 0:000 Found NVidia model=EVGA GeForce 8400 GS  
4:784 0:000 PCI (00101:00.01) : 10DE 0BE3 class=040300  
4:784 0:000 PCI (00100:02.00) : 8086 0152 class=038000  
4:784 0:000 PCI (00100:16.00) : 8086 1C3A class=078000  
4:784 0:000 PCI (00100:1A.00) : 8086 1C2D class=0C0320  
4:784 0:000 PCI (00100:1B.00) : 8086 1C20 class=040300  
4:784 0:000 PCI (00100:1C.00) : 8086 1C10 class=060400  
4:784 0:000 PCI (00100:1C.03) : 8086 1C16 class=060400  
4:784 0:000 PCI (00103:00.00) : 10EC 8168 class=020000  
4:784 0:000 LAN 0, Vendor=10EC, MMIO=D000  
4:784 0:000 PCI (00100:1C.05) : 8086 1C1A class=060400  
4:784 0:000 PCI (00104:00.00) : 1B21 1042 class=0C0330  
4:784 0:000 PCI (00100:1D.00) : 8086 1C26 class=0C0320  
4:784 0:000 PCI (00100:1F.00) : 8086 1C5C class=060100  
4:785 0:000 PCI (00100:1F.02) : 8086 1C02 class=010601  
4:785 0:000 PCI (00100:1F.03) : 8086 1C22 class=0C0500  
4:785 0:000 Clover load options size = 0 bytes  
4:806 0:021 Using OEM config.plist at path: EFI\CLOVER\config.plist  
4:806 0:000 EFI\CLOVER\config.plist loaded: Success  
4:806 0:000 Found theme directory: embedded  
4:806 0:000 Found theme directory: random  
4:807 0:001 Found theme directory: tonymacx86  
4:810 0:002 Loading early settings  
4:810 0:000 timeout set to 5  
4:810 0:000 Custom boot CUSTOM\_BOOT\_DISABLED (0x0)  
4:810 0:000 KextsToPatch: 3 requested  
4:810 0:000 KextToPatch 0: AppleHDA (t1-10.11-AppleHDA/Realtek ALC...) Kext  
bin patch, data len: 4  
4:810 0:000 KextToPatch 1: AppleHDA (t1-10.9-10.11-AppleHDA/Realtek ALC887)  
Kext bin patch, data len: 4  
4:810 0:000 KextToPatch 2: AppleHDA (t1-AppleHDA/Resources/xml>zml) Kext bin  
patch, data len: 6  
4:810 0:000 Default theme: embedded  
4:810 0:000 LoadDrivers() start  
4:810 0:000 Loading FSInject-64.efi status=Success  
4:817 0:007 Video bios patch requested or CustomEDID - forcing video reconnect  
4:817 0:000 1 drivers needs connecting ...  
4:817 0:000 PlatformDriverOverrideProtocol->GetDriver overriden  
4:817 0:000 Video driver loaded: disconnect Success  
4:893 0:075 VideoBiosPatchNativeFromEdid:

4:893 0:000 Edid: not found  
4:898 0:005 BiosVideoDriverBindingStart!  
4:898 0:000 BiosVideoCheckForVbe  
4:898 0:000 EdidOverride not found  
5:042 0:143 Edid1-  
5:186 0:143 Edid0-  
5:212 0:026 0 640x480 attr=3BF - ok, 640x480, working, highest, pref=0  
5:213 0:001 1 800x600 attr=3BF - ok, 800x600, working, highest, pref=1  
5:214 0:001 2 1024x768 attr=3BF - ok, 1024x768, working, highest, pref=2  
5:219 0:004 BV new mode: 2 1024x768  
5:359 0:140 SetMode pref 2 (2) = Success  
5:481 0:121 LoadDrivers() end  
5:481 0:000 SetScreenResolution: 1360x768 - not found!  
5:481 0:000 Console modes reported: 4, available modes:  
5:481 0:000 Mode 1: 80x25  
5:481 0:000 Mode 3: 100x31  
5:481 0:000 Mode 4: 128x40 (current mode)  
5:481 0:000 SetScreenResolution: 1024x768 - already set  
5:481 0:000 reinit: self device path=PcieRoot(0x0)\Pci(0x1F,  
0x2)\Sata(0x1,0x0,0x0)\HD(1,GPT,7460A46D-6F4E-4AED-A1B6-E20225C09D7B,  
0x28,0x64000)  
5:481 0:000 ScanSPD() start  
5:482 0:000 SMBus CmdReg: 0x3  
5:482 0:000 Scanning SMBus [8086:1C22], mmio: 0xF7905004, ioport: 0xF040,  
hostc: 0x1  
5:482 0:000 Slots to scan [8]...  
5:496 0:014 SPD[0]: Type 11 @0x50  
5:504 0:008 Found module with XMP version 1.3DDR speed 1600MHz  
5:504 0:000 Slot: 0 Type 24 4096MB 1600MHz Vendor=Kingston  
PartNo=KHX1600C9D34GX SerialNo=000A03080C04060A  
5:524 0:020 SPD[2]: Type 11 @0x52  
5:533 0:008 DDR speed 1333MHz  
5:533 0:000 Slot: 2 Type 24 2048MB 1333MHz Vendor=Kingston  
PartNo=99U5402-061.A00LF SerialNo=0B05010D02020704  
5:563 0:030 ScanSPD() end  
5:568 0:004 Get Acpi Tables List from RSDT:  
5:568 0:000 Found table: FACP A M I len=132  
5:568 0:000 Found table: APIC A M I len=98  
5:568 0:000 Found table: FPDT A M I len=68  
5:568 0:000 Found table: MCFG A M I len=60  
5:568 0:000 Found table: SSDT AoacTabl len=2017  
5:568 0:000 Found table: AAFT OEMAAFT len=234  
5:568 0:000 Found table: HPET A M I len=56  
5:568 0:000 Found table: SSDT SataTabl len=877  
5:568 0:000 Found table: SSDT Cpu0lst len=2474  
5:568 0:000 Found table: SSDT CpuPm len=2706  
5:568 0:000 Found table: BGRT A M I len=56  
5:568 0:000 Calibrated TSC frequency =3092976240 =3092MHz  
5:568 0:000 Loading main settings  
5:568 0:000 Config set Fixes will override FixMask mask!

5:568 0:000 final mask=00001100  
5:568 0:000 Config set ResetAddr=0x0  
5:568 0:000 Config calc ResetVal=0x0  
5:568 0:000 Config set ResetVal=0x0  
5:568 0:000 Config set ChassisType=0xD  
5:568 0:000 Config set QPI = 0 disable table132  
5:568 0:000 Config set CpuFreq=3100MHz  
5:568 0:000 Config set CpuType=0  
5:568 0:000 Config set BusSpeed=99773kHz  
5:568 0:000 Error: invalid CustomUUID " - should be in the format XXXXXXXX-XXXX-XXXX-XXXX-XXXXXXXXXXXX  
5:568 0:000 found 12 volumes with blockIO  
5:568 0:000 0. Volume:  
5:568 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x0,0x0,0x0)  
5:569 0:000 1. Volume:  
5:569 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x1,0x0,0x0)  
5:569 0:000 Result of bootcode detection: bootable unknown (legacy)  
5:569 0:000 2. Volume:  
5:569 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x0,0x0,0x0)\HD(1,GPT,F6B2010C-CFF5-431E-9DC0-153B3A34B251,0x800,0x96000)  
5:569 0:000 Result of bootcode detection: bootable Windows (vista,win)  
5:569 0:000 3. Volume:  
5:569 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x0,0x0,0x0)\HD(2,GPT,4922A41F-E4D8-4F51-8E0B-481DA223CC6B,0x96800,0x32000)  
5:570 0:000 Result of bootcode detection: bootable Windows (vista,win)  
5:570 0:000 4. Volume:  
5:570 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x0,0x0,0x0)\HD(3,GPT,E70BF38D-44ED-45FB-B8B9-25937116D6D9,0xC8800,0x40000)  
5:570 0:000 5. Volume:  
5:570 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x0,0x0,0x0)\HD(4,GPT,D7F0F140-CD3C-475A-8344-1634FAFB668F,0x108800,0x1DB09800)  
5:570 0:000 Result of bootcode detection: bootable Windows (vista,win)  
5:570 0:000 6. Volume:  
5:570 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x0,0x0,0x0)\HD(5,GPT,D09F9619-ECAC-4179-A171-1C9251E39AE3,0x1DC12000,0xE1000)  
5:570 0:000 Result of bootcode detection: bootable Windows (vista,win)  
5:570 0:000 7. Volume:  
5:570 0:000 PcieRoot(0x0)\Pci(0x1D,0x0)\USB(0x0,0x0)\USB(0x0,0x0)  
5:573 0:003 USB volume  
5:573 0:000 USB volume  
5:573 0:000 8. Volume:  
5:573 0:000 PcieRoot(0x0)\Pci(0x1D,0x0)\USB(0x0,0x0)\USB(0x0,0x0)\HD(1,MBR,0xFECFB1CE,0x2,0x74706DAE)  
5:577 0:003 Result of bootcode detection: bootable unknown (legacy)  
5:577 0:000 USB volume  
5:577 0:000 USB volume

6:643 1:066 9. Volume:  
6:643 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x1,0x0,0x0)\HD(1,GPT,  
7460A46D-6F4E-4AED-A1B6-E20225C09D7B,0x28,0x64000)  
6:643 0:000 Result of bootcode detection: bootable Clover (clover)  
6:643 0:000 This is SelfVolume !!  
6:643 0:000 10. Volume:  
6:643 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x1,0x0,0x0)\HD(2,GPT,  
13DDF62D-BA72-4B89-A17C-C3E83DE41DEB,0x64028,0x7456CE40)  
6:644 0:000 11. Volume:  
6:644 0:000 PcieRoot(0x0)\Pci(0x1F,0x2)\Sata(0x1,0x0,0x0)\HD(3,GPT,  
0D18AFDD-173F-4B53-B24D-0605C28A68F7,0x745D0E68,0x135F20)  
8:799 2:155 PutNvramPlistToRtVars: nvram.plist not found  
8:799 0:000 using embedded theme  
8:800 0:000 Choosing theme <null string>  
8:800 0:000 Custom entries start  
8:800 0:000 Custom entries finish  
8:800 0:000 Scanning loaders...  
8:800 0:000 0: 'Whole Disc Boot' no file system  
8:800 0:000 1: 'Whole Disc Boot' no file system  
8:800 0:000 2: 'Legacy HD1' no file system  
8:800 0:000 3: 'EFI'  
8:802 0:002 AddLoaderEntry for Volume Name=EFI  
8:804 0:001 4: 'Legacy HD3' no file system  
8:804 0:000 5: 'Legacy HD4' no file system  
8:804 0:000 6: 'Legacy HD5' no file system  
8:804 0:000 7: 'Whole Disc Boot' no file system  
8:804 0:000 8: 'Opslag'  
38:655 29:850 9: 'EFI'  
38:665 0:010 10: 'Macintosh HD'  
38:687 0:022 AddLoaderEntry for Volume Name=Macintosh HD  
38:700 0:013 Check if volume Is Hibernated:  
38:700 0:000 Check sleep image 'by signature':  
38:725 0:024 read prefs \Library\Preferences\SystemConfiguration  
\com.apple.PowerManagement.plist status=Success  
38:725 0:000 SleepImage name from pref: ImageVolume = 'Macintosh HD',  
ImageName = '\private\var\vm\sleepimage'  
38:762 0:036 Reading first 512 bytes of sleepimage ...  
38:773 0:011 OurBlockIoRead: Lba=2F24438, Offset=5E4887000 (BlockSize=512)  
38:773 0:000 sig lion: 8000000  
38:773 0:000 sig snow: 3000000  
38:773 0:000 no valid sleep image offset was found  
38:773 0:000 Reading completed -> Success  
38:773 0:000 sleepimage offset could not be acquired  
38:773 0:000 hibernated: no - sign  
38:776 0:003 11: 'Recovery HD'  
38:777 0:000 AddLoaderEntry for Volume Name=Recovery HD  
38:804 0:027 Custom legacy start  
38:804 0:000 Custom legacy end  
38:804 0:000 Scanning legacy ...  
38:804 0:000 0: 'Whole Disc Boot' (legacy) not legacy

38:804 0:000 1: 'Whole Disc Boot' (legacy) not legacy  
38:804 0:000 2: 'Legacy HD1' (vista,win) add legacy  
38:804 0:000 added 'Boot Windows from Legacy HD1' OStype=2 Icon=vista,win  
38:804 0:000 3: 'EFI' (vista,win) add legacy  
38:804 0:000 added 'Boot Windows from EFI' OStype=2 Icon=vista,win  
38:804 0:000 4: 'Legacy HD3' (legacy) not legacy  
38:804 0:000 5: 'Legacy HD4' (vista,win) add legacy  
38:804 0:000 added 'Boot Windows from Legacy HD4' OStype=2 Icon=vista,win  
38:804 0:000 6: 'Legacy HD5' (vista,win) add legacy  
38:804 0:000 added 'Boot Windows from Legacy HD5' OStype=2 Icon=vista,win  
38:804 0:000 7: 'Whole Disc Boot' (legacy) not legacy  
38:804 0:000 8: 'Opslag' (legacy) not legacy  
38:804 0:000 9: 'EFI' (clover) add legacy  
38:805 0:001 added 'Boot Clover from EFI' OStype=3 Icon=clover  
38:805 0:000 10: 'Macintosh HD' (legacy) not legacy  
38:805 0:000 11: 'Recovery HD' (legacy) not legacy  
38:806 0:000 Custom tool start  
38:806 0:000 Custom tool end  
38:806 0:000 found tool \EFI\CLOVER\tools\Shell64U.efi  
38:806 0:000 Checking EFI partition Volume 3 for Clover  
38:806 0:000 Checking EFI partition Volume 9 for Clover  
38:806 0:000 Found Clover  
38:807 0:000 GetEfiBootDeviceFromNvram: efi-boot-device-data not found  
38:807 0:000 EfiBootVolume not found  
38:807 0:000 found entry 1. 'Boot Mac OS X from Macintosh HD', Volume  
'Macintosh HD', DevicePath 'PcieRoot(0x0)\Pci(0x1F,  
0x2)\Sata(0x1,0x0,0x0)\HD(2,GPT,13DDF62D-BA72-4B89-A17C-C3E83DE41DEB,  
0x64028,0x7456CE40)\System\Library\CoreServices\boot.efi'  
38:807 0:000 DefaultIndex=1 and MainMenu.EntryCount=14  
38:862 0:054 Found Mouse device:  
38:862 0:000 GUI ready  
45:016 6:153 StartLoader() start  
45:016 0:000 Entry->Settings: <null string>  
45:016 0:000 Finally: Bus=99773kHz CPU=3100MHz  
45:016 0:000 Kernel and Kext Patches at 1F7D73B0:  
45:016 0:000 Allowed: y  
45:016 0:000 Debug: n  
45:016 0:000 KernelCpu: n  
45:016 0:000 Lpic: n  
45:016 0:000 Haswell-E: n  
45:016 0:000 AICPUPM: n  
45:016 0:000 AppleRTC: n  
45:016 0:000 KernelPm: n  
45:016 0:000 FakeCPUID: 0x0  
45:016 0:000 ATIController: null  
45:016 0:000 ATIDataLength: 0  
45:016 0:000 0 Kexts to load  
45:016 0:000 3 Kexts to patch  
45:016 0:000 KextPatch[0]: 4 bytes, AppleHDA  
45:016 0:000 KextPatch[1]: 4 bytes, AppleHDA

```

45:016 0:000 KextPatch[2]: 6 bytes, AppleHDA
45:016 0:000 Loading boot.efi status=Success
45:095 0:078 GetOSVersion: : 10.11.1
45:095 0:000 insert table 9 for dev 0:0
45:095 0:000 insert table 9 for dev 0:1
45:095 0:000 insert table 9 for dev 0:0
45:095 0:000 Detected alternating SMBIOS channel banks
45:095 0:000 Channels: 2
45:095 0:000 Interleave: 0 2 1 3 4 6 5 7
45:095 0:000 SMBIOS Type 17 Index = 0 => 0 0:
45:095 0:000 BANK0 DIMM0 1600MHz 4096MB
45:095 0:000 mTotalSystemMemory = 4096
45:095 0:000 SMBIOS Type 17 Index = 1 => 1 2:
45:095 0:000 BANK1 DIMM0 1333MHz 2048MB
45:095 0:000 mTotalSystemMemory = 6144
45:095 0:000 NumberOfMemoryDevices = 2
45:095 0:000 Type20[0]->End = 0x3FFFFFF, Type17[0] = 0x1000
45:095 0:000 Type20[1]->End = 0x5FFFFFF, Type17[1] = 0x2800
45:095 0:000 Table 131 is present, CPUType=10
45:095 0:000 Change to: 0
45:095 0:000 RSDT 0xCA1DB028
45:095 0:000 FADT from RSDT: 0xCA1DB108
45:095 0:000 XSDT 0xCA1DB080
45:095 0:000 FADT from XSDT: 0xCA1E47D8
45:095 0:000 Xsdt reallocation done
45:095 0:000 old FADT length=10C
45:095 0:000 Found OperationRegion(GNVS, SystemMemory, CA1F3E18, ...)
45:095 0:000 Found OperationRegion(S4NV, SystemMemory, CA1F5E98, ...)
45:095 0:000 Found OperationRegion(MCHT, SystemMemory, FED10000, ...)
45:095 0:000 Found OperationRegion(RCRB, SystemMemory, FED1C000, ...)
45:095 0:000 Found OperationRegion(CPSB, SystemMemory, CA0CFE18, ...)
45:095 0:000 Found OperationRegion(IGDM, SystemMemory, 0, ...)
45:095 0:000 Found OperationRegion(TMMB, SystemMemory, FED40000, ...)
45:095 0:000 Found OperationRegion(TVID, SystemMemory, FED40F00, ...)
45:095 0:000 Found OperationRegion(TPMR, SystemMemory, FED40000, ...)
45:096 0:000 DSDT found in Clover volume OEM folder: EFI\CLOVER\ACPI
\patched\dsdt.aml
45:106 0:010 Apply DsdtFixMask=0x00001100 old way
45:106 0:000 drop _DSM mask=0x0000
45:106 0:000 ===== Auto patch DSDT Starting =====
45:106 0:000 VideoCard devID=0x10C310DE
45:106 0:000 DisplayADR1[0] = 0x10000, DisplayADR2[0] = 0x0
45:106 0:000 USBADR[0] = 0x1A0000 and PCIe = 0xFFFFE
45:106 0:000 Audio HDA (addr:0x1B0000) setting specified layout-id=2 (0x2)
45:106 0:000 USBADR[1] = 0x1C0005 and PCIe = 0x0
45:106 0:000 USBADR[2] = 0x1D0000 and PCIe = 0xFFFFE
45:106 0:000 first CPU found at 76A3 offset 76A6
45:106 0:000 score candidate at 769F
45:106 0:000 score inserted in acpi_cpu_score_PR_
45:106 0:000 Found ACPI CPU: CPU0 And CPU1 And CPU2 And CPU3 And CPU4

```

And CPU5 And CPU6 And CPU7

within the scope: \_PR\_

```
45:106 0:000 Found PCIROOTUID = 0
45:107 0:000 Start Display0 Fix
45:107 0:000 Found internal video device 0 @3E77
45:107 0:000 _DSM already exists, patch display will not be applied
45:107 0:000 now inserting Video device
45:107 0:000 ... into existing bridge
45:107 0:000 patch Display #0 of Vendor=0x10DE in DSDT old way
45:107 0:000 Start HDMI139 Fix
45:107 0:000 found HDMI device [0x00010000:1] at 405C and Name is HDAU
45:107 0:000 NewName HDAU already present, renaming impossible
45:107 0:000 _DSM already exists, patch HDAU will not be applied
45:107 0:000 Start USB Fix
45:107 0:000 USB bridge[1A0000] at 4A60, size = 3A0
45:107 0:000 found slave _DSM, skip
45:108 0:000 USB bridge[1C0005] at 3BB1, size = DD
45:108 0:000 USB bridge[1D0000] at 4601, size = 53A
45:108 0:000 found slave _DSM, skip
45:108 0:000 ===== Auto patch DSDT Finished =====
45:108 0:000 Patch table: SSDT AoacTabl
45:108 0:000 SSDT len = 0x7E1
45:108 0:000 Patch table: SSDT SataTabl
45:108 0:000 SSDT len = 0x36D
45:108 0:000 Patch table: SSDT Cpu0Ist
45:108 0:000 SSDT len = 0x9AA
45:108 0:000 Patch table: SSDT CpuPm
45:108 0:000 SSDT len = 0xA92
45:108 0:000 Drop tables from Xsdt, SIGN=XXXX TableID= Length=0
45:108 0:000 Xsdt has tables count=11
45:108 0:000 corrected XSDT length=124
45:108 0:000 Inserting dsdt.aml from EFI\CLOVER\ACPI\patched ... Success
45:109 0:000 CPUBase=0 and ApicCPUBase=1 ApicCPUNum=2
45:109 0:000 EdidDiscovered size=0
45:109 0:000 NVidia GFX injection not set
45:109 0:000 HDA Controller [8086:1C20] :: PciRoot(0x0)\Pci(0x1B,0x0) =>
setting specified layout-id=2 (0x2)
45:109 0:000 LAN Controller [10EC:8168] :: PciRoot(0x0)\Pci(0x1C,
0x3)\Pci(0x0,0x0)
45:109 0:000 stringlength = 552
45:109 0:000 CurrentMode: Width=1024 Height=768
45:109 0:000 FSInjection: using kexts path: 'EFI\CLOVER\kexts
\10.11'FSInjectionInstall ...
- Our FSI_SIMPLE_FILE_SYSTEM_PROTOCOL installed on handle: 1F47CB98
45:110 0:000
45:111 0:000 Preparing kexts injection for arch=x86_64 from EFI\CLOVER\kexts
\10.11
45:112 0:001 Extra kext: EFI\CLOVER\kexts\10.11\FakeSMC.kext
45:113 0:001 Extra kext: EFI\CLOVER\kexts\10.11\RealtekRTL8111.kext
45:123 0:009 Removed efi-boot-device-data variable: Not Found
```



45:123 0:000 Custom boot screen not used because entry has unset use graphics  
45:123 0:000 Closing log