

Anonymous UUID: D6917631-BF91-950E-EC8D-8512FBF71138

Fri Jan 25 18:49:18 2019

*** Panic Report ***

panic(cpu 0 caller 0xfffff8017eda29d): Kernel trap at 0xfffff7f9ac39215, type 14=page fault, registers:
CR0: 0x000000008001003b, CR2: 0x0000000000000138, CR3: 0x0000000041bfd05f, CR4: 0x000000000003626e0
RAX: 0x0000000000000000, RBX: 0xfffff805ab3fee0, RCX: 0x00000000ffffff, RDX: 0x00000000fffecb4f
RSP: 0xfffff924185b3e0, RBP: 0xfffff924185b400, RSI: 0x0000000000000021, RDI: 0xfffff805ab3fee0
R8: 0x0000000000000000, R9: 0x0000000000000000, R10: 0xfffff801869deb0, R11: 0xfffff80187edc80
R12: 0x00000000000000210, R13: 0x0000000000000021, R14: 0xfffff805d328b00, R15: 0x00000000000000210
RFL: 0x0000000000010282, RIP: 0xfffff7f9ac39215, CS: 0x0000000000000008, SS: 0x0000000000000010
Fault CR2: 0x0000000000000138, Error code: 0x0000000000000000, Fault CPU: 0x0, PL: 0, VF: 0

Backtrace (CPU 0), Frame : Return Address

0xfffff924185aeb0 : 0xfffff8017daeb0d mach_kernel : _handle_debugger_trap + 0x48d
0xfffff924185af00 : 0xfffff8017ee8653 mach_kernel : _kdp_i386_trap + 0x153
0xfffff924185af40 : 0xfffff8017eda07a mach_kernel : _kernel_trap + 0x4fa
0xfffff924185afb0 : 0xfffff8017d5bca0 mach_kernel : _return_from_trap + 0xe0
0xfffff924185afd0 : 0xfffff8017dae527 mach_kernel : _panic_trap_to_debugger + 0x197
0xfffff924185b0f0 : 0xfffff8017dae373 mach_kernel : _panic + 0x63
0xfffff924185b160 : 0xfffff8017eda29d mach_kernel : _kernel_trap + 0x71d
0xfffff924185b2d0 : 0xfffff8017d5bca0 mach_kernel : _return_from_trap + 0xe0
0xfffff924185b2f0 : 0xfffff7f9ac39215 com.apple.kext.AMDRadeonX4000 :
__ZN35AMDRadeonX4000_AMDCommandBufferPool13prepareBufferEj + 0x27
0xfffff924185b400 : 0xfffff7f9ac39494 com.apple.kext.AMDRadeonX4000 :
__ZN35AMDRadeonX4000_AMDCommandBufferPool13getNextBufferEv + 0xc2
0xfffff924185b440 : 0xfffff7f9ac39729 com.apple.kext.AMDRadeonX4000 :
__ZN35AMDRadeonX4000_AMDCommandBufferPool12submitBufferEy + 0x155
0xfffff924185b470 : 0xfffff7f9ac37252 com.apple.kext.AMDRadeonX4000 :
__ZN35AMDRadeonX4000_AMDAtomicBlitManager18endBatchSubmissionEy + 0x20
0xfffff924185b490 : 0xfffff7f9ac1b00f com.apple.kext.AMDRadeonX4000 :
__ZN31AMDRadeonX4000_AMDAccelResource6pageonEP12IOAccelEventby + 0x37d
0xfffff924185b550 : 0xfffff7f99f30a9e com.apple.iokit.IOAcceleratorFamily2 :
__ZN16IOAccelResource214pageonIfNeededEv + 0x14c
0xfffff924185b5d0 : 0xfffff7f99f3054b com.apple.iokit.IOAcceleratorFamily2 :
__ZN16IOAccelResource24loadEv + 0x25
0xfffff924185b5f0 : 0xfffff7f99f32acc com.apple.iokit.IOAcceleratorFamily2 :

```

__ZN16IOAccelResource27prepareEv + 0x194
0xffffffff924185b630 : 0xffffffff7f9ac1f987 com.apple.kext.AMDRadeonX4000 :
__ZN31AMDRadeonX4000_AMDAccelResource7prepareEv + 0x47
0xffffffff924185b650 : 0xffffffff7f99f3bc3e com.apple.iokit.IOAcceleratorFamily2 :
__ZN26IOAccelSegmentResourceList7prepareEv + 0x30
0xffffffff924185b680 : 0xffffffff7f99f4fe94 com.apple.iokit.IOAcceleratorFamily2 :
__ZN19IOAccelCommandQueue15coalesceSegmentEP26IOAccelCommandQueue
SegmentPjP26IOAccelSegmentResourceListPK20IOAccelKernelCommandS7_ +
0x4e
0xffffffff924185b6c0 : 0xffffffff7f99f501ce com.apple.iokit.IOAcceleratorFamily2 :
__ZN19IOAccelCommandQueue20processCommandBufferEjj + 0x29a
0xffffffff924185b660 : 0xffffffff7f99f51188 com.apple.iokit.IOAcceleratorFamily2 :
__ZN19IOAccelCommandQueue22process_command_bufferEjj + 0x39c
0xffffffff924185b9f0 : 0xffffffff7f99f4f4c0 com.apple.iokit.IOAcceleratorFamily2 :
__ZN19IOAccelCommandQueue21submit_command_bufferEjjyy + 0xfc
0xffffffff924185ba50 : 0xffffffff7f99f4f2b9 com.apple.iokit.IOAcceleratorFamily2 :
__ZN19IOAccelCommandQueue22submit_command_buffersEPK29IOAccelComma
ndQueueSubmitArgs + 0x33b
0xffffffff924185baa0 : 0xffffffff7f99f4e2f4 com.apple.iokit.IOAcceleratorFamily2 :
__ZN19IOAccelCommandQueue24s_submit_command_buffersEPS_PvP25IOExter
nalMethodArguments + 0xfa
0xffffffff924185bae0 : 0xffffffff8018485858 mach_kernel :
__ZN12IOUserClient14externalMethodEjP25IOExternalMethodArgumentsP24IOExt
ernalMethodDispatchP8OSObjectPv + 0x1d8
0xffffffff924185bb30 : 0xffffffff801848ecdf mach_kernel : _is_io_connect_method +
0x20f
0xffffffff924185bc70 : 0xffffffff8017e94c64 mach_kernel : _iokit_server_routine +
0x5e84
0xffffffff924185bd80 : 0xffffffff8017db43ed mach_kernel : _ipc_kobject_server + 0x12d
0xffffffff924185bdd0 : 0xffffffff8017d8ebe5 mach_kernel : _ipc_kmsg_send + 0x225
0xffffffff924185be50 : 0xffffffff8017da35ae mach_kernel : _mach_msg_overwrite_trap +
0x38e
0xffffffff924185bef0 : 0xffffffff8017ec17bb mach_kernel : _mach_call_munger64 +
0x22b
0xffffffff924185bfa0 : 0xffffffff8017d5c486 mach_kernel : _hndl_mach_scall64 + 0x16
    Kernel Extensions in backtrace:
        com.apple.iokit.IOAcceleratorFamily2(404.2.2)[3F0DBC5F-414B-379E-8C7B-
A2F50B278A2A]@0xffffffff7f99f18000->0xffffffff7f99fbcfff
            dependency: com.apple.driver.AppleMobileFileIntegrity(1.0.5)
[A2492141-9480-3177-BC7D-455925BB4A2E]@0xffffffff7f98b82000
            dependency: com.apple.iokit.IOSurface(255.1)[12B5957C-3874-3A96-8FC6-
FAC2180790A9]@0xffffffff7f99ef4000
            dependency: com.apple.iokit.IOPCIFamily(2.9)[5C9A453F-559B-3683-9E81-
D288D13A33CE]@0xffffffff7f98695000
            dependency: com.apple.iokit.IOGraphicsFamily(530.14)
[D44517BE-2B53-3BD5-826E-4E78B55E3B73]@0xffffffff7f98e25000
            dependency: com.apple.iokit.IOReportFamily(47)[5F165AE5-
F4F2-3415-857C-34F2462A730E]@0xffffffff7f994c9000
        com.apple.kext.AMDRadeonX4000(2.0.4)
[72D8FB63-8A63-38CB-8D53-01E07205BCAE]@0xffffffff7f9ac0c000-

```

>0xffffffff7f9b1c7fff

dependency: com.apple.iokit.IOSurface(255.1)[12B5957C-3874-3A96-8FC6-FAC2180790A9]@0xffffffff7f99ef4000

dependency: com.apple.iokit.IOPCIFamily(2.9)[5C9A453F-559B-3683-9E81-D288D13A33CE]@0xffffffff7f98695000

dependency: com.apple.iokit.IOGraphicsFamily(530.14)
[D44517BE-2B53-3BD5-826E-4E78B55E3B73]@0xffffffff7f98e25000

dependency: com.apple.iokit.IOAcceleratorFamily2(404.2.2)
[3F0DBC5F-414B-379E-8C7B-A2F50B278A2A]@0xffffffff7f99f18000

BSD process name corresponding to current thread: WindowServer

Boot args: keepsyms=1 dart=0 debug=0x100 shikigva=40

Mac OS version:

18D42

Kernel version:

Darwin Kernel Version 18.2.0: Thu Dec 20 20:46:53 PST 2018;

root:xnu-4903.241.1~1/RELEASE_X86_64

Kernel UUID: 1970B070-E53F-3178-83F3-1B95FA340695

Kernel slide: 0x0000000017a00000

Kernel text base: 0xffffffff8017c00000

__HIB text base: 0xffffffff8017b00000

System model name: iMac17,1 (Mac-B809C3757DA9BB8D)

System uptime in nanoseconds: 1815290041587

last loaded kext at 248333308612: com.apple.filesystems.msdosfs

1.10 (addr 0xffffffff7f98e82000, size 69632)

loaded kexts:

com.no-one.BrcmPatchRAM2 2.2.7

com.no-one.BrcmFirmwareStore 2.2.7

org.rehabman.driver.FakePCIID1.3.11

com.insanelymac.IntelMausiEthernet 2.4.1d1

org.hwsensors.driver.LPCSensors 1800

org.hwsensors.driver.GPUSensors 1800

org.hwsensors.driver.ACPI Sensors 1800

org.hwsensors.driver.SMMSensors 1800

org.hwsensors.driver.CPUSensors 1800

as.vit9696.WhateverGreen 1.2.6

org.netkas.driver.FakeSMC 1800

as.vit9696.AppleALC 1.3.4

as.vit9696.Lilu 1.3.1

com.apple.filesystems.msdosfs 1.10

com.apple.driver.AudioAUUC 1.70

com.apple.fileutil 18.306.12

com.apple.kext.AMDFramebuffer 2.0.4

com.apple.filesystems.autofs 3.0

com.apple.driver.AppleUpstreamUserClient 3.6.5

com.apple.driver.AppleMCCSCControl 1.5.6

com.apple.driver.ApplePlatformEnabler 2.7.0d0

com.apple.driver.X86PlatformShim 1.0.0
com.apple.driver.AGPM 110.23.46
com.apple.driver.AppleHDAHardwareConfigDriver 282.10
com.apple.driver.AppleHDA 282.10
com.apple.kext.AMDRadeonX4000 2.0.4
com.apple.driver.AppleGraphicsDevicePolicy 3.28.4
com.apple.AGDCPluginDisplayMetrics 3.28.4
com.apple.driver.AppleIntelSKLGraphics 12.0.4
com.apple.driver.AppleHV 1
com.apple.iokit.IOUserEthernet 1.0.1
com.apple.iokit.IOBluetoothSerialManager 6.0.10f1
com.apple.driver.pmtelemetry 1
com.apple.Dont_Steal_Mac_OS_X 7.0.0
com.apple.kext.AMD9500Controller 2.0.4
com.apple.driver.AppleIntelPCHPMC 2.0.1
com.apple.driver.AppleGFXHDA 100.1.40
com.apple.driver.AppleFIVRDriver 4.1.0
com.apple.driver.AppleIntelSKLGraphicsFramebuffer 12.0.4
com.apple.driver.AppleIntelSlowAdaptiveClocking 4.0.0
com.apple.driver.AppleOSXWatchdog 1
com.apple.driver.ACPI_SMC_PlatformPlugin 1.0.0
com.apple.filesystems.apfs 945.241.4
com.apple.driver.AppleFileSystemDriver 3.0.1
com.apple.driver.AppleVirtIO 2.1.3
com.apple.filesystems.hfs.kext 407.200.4
com.apple.AppleFSCompression.AppleFSCompressionTypeDataless
1.0.0d1
com.apple.BootCache 40
com.apple.AppleFSCompression.AppleFSCompressionTypeZlib
1.0.0
com.apple.AppleSystemPolicy 1.0
com.apple.driver.AirPort.Brcm4360 1400.1.1
com.apple.driver.AppleAHCIPort 329.200.2
com.apple.private.KextAudit 1.0
com.apple.driver.AppleRTC 2.0
com.apple.driver.AppleACPIButtons 6.1
com.apple.driver.AppleHPET 1.8
com.apple.driver.AppleSMBIOS 2.1
com.apple.driver.AppleAPIC 1.7
com.apple.nke.applicationfirewall 190
com.apple.security.TMSafetyNet 8
com.apple.kext.triggers 1.0
com.apple.iokit.BroadcomBluetoothHostControllerUSBTransport
6.0.10f1
com.apple.iokit.IOBluetoothHostControllerUSBTransport 6.0.10f1
com.apple.iokit.IOBluetoothHostControllerTransport 6.0.10f1
com.apple.driver.AppleSMBusController 1.0.18d1
com.apple.iokit.IOSMBusFamily 1.1
com.apple.driver.DspFuncLib 282.10
com.apple.kext.OSvKernDSPLib 527

com.apple.kext.AMDRadeonX4000HWLibs 1.0
com.apple.kext.AMDRadeonX4000HWServices 2.0.4
com.apple.driver.AppleGraphicsControl 3.28.4
com.apple.iokit.IOAVBFamily 710.1
com.apple.plugin.IOGPTPlugin 700.7
com.apple.iokit.IOEthernetAVBController 1.1.0
com.apple.driver.AppleSSE 1.0
com.apple.iokit.IOBluetoothFamily 6.0.10f1
com.apple.AppleGPUWangler 3.28.4
com.apple.driver.AppleHDAController 282.10
com.apple.iokit.IOHDAFamily 282.10
com.apple.iokit.IONDRVSupport 530
com.apple.kext.AMDSupport 2.0.4
com.apple.AppleGraphicsDeviceControl 3.28.4
com.apple.iokit.IOAcceleratorFamily2 404.2.2
com.apple.iokit.IOGraphicsFamily 530.14
com.apple.iokit.IOSurface 255.1
com.apple.iokit.IOSlowAdaptiveClockingFamily 1.0.0
com.apple.driver.AppleSMBusPCI 1.0.14d1
com.apple.driver.IOPlatformPluginLegacy 1.0.0
com.apple.driver.X86PlatformPlugin 1.0.0
com.apple.driver.IOPlatformPluginFamily 6.0.0d8
com.apple.driver.AppleXsanScheme 3
com.apple.iokit.IOAHCIBlockStorage 30

EOF

Model: iMac17,1, BootROM 161.0.0.0.0, 4 processors, Intel Core i7, 3,41 GHz, 16 GB, SMC 2.33f10

Graphics: Radeon RX 580, Radeon RX 580, PCIe

Memory Module: BANK 0/DIMM0, 8 GB, DDR4, 2133 MHz, Crucial Technology, CT8G4DFD8213.C16FAR2

Memory Module: BANK 1/DIMM0, 8 GB, DDR4, 2133 MHz, Crucial Technology, CT8G4DFD8213.C16FAR2

AirPort: spairport_wireless_card_type_airport_extreme (0x14E4, 0x623), Broadcom BCM43xx 1.0 (7.21.190.32 AirPortDriverBrcm4360-1315.1)

Bluetooth: Version 6.0.10f1, 3 services, 27 devices, 1 incoming serial ports

Serial ATA Device: CT500MX500SSD1, 500,11 GB

USB Device: USB 3.0 Bus

USB Device: BCM20702A0

USB Device: USB Keyboard

USB Device: Microsoft® Nano Transceiver v2.0

Thunderbolt Bus: